

# Risk assessment: C & S PPFA Ltd

# Outside Toilets

Assessment carried out by: **Annie Blake** Date assessment was carried out: **05/12/2023**

Date of next review: **01/09/2024**

Date signed off by committee: **28/11/2023**

What are the hazards?	Who might be harmed and how?	What are we Already doing to control the risks?	What further action Do we need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?	Done
<b>Electricity</b> 240v supply to lighting, wall sockets, driers in toilets,	<ul style="list-style-type: none"> <li>• Users &amp; maintenance personnel</li> <li>• Children</li> <li>• Electrocution and/or burns</li> <li>• Electrical equipment damaged</li> </ul>	<ul style="list-style-type: none"> <li>• System designed, installed and certified by qualified electricians, to conform with Building Regs</li> <li>• Electrical Installation Condition Report produced every five years</li> <li>• Consumer unit mounted at eye level</li> </ul>	N/A	N/A	N/A	N/A
<b>Slips, trips &amp; falls</b>	<ul style="list-style-type: none"> <li>• Users &amp; maintenance personnel</li> <li>• Trip over paers elt on floor</li> <li>• wet floor</li> </ul>	<ul style="list-style-type: none"> <li>• Toilets cleaned on a regular basis and users are asked to keep the toilets tidy</li> <li>• toilet floors have 'non slip' surfaces.</li> </ul>	N/A	N/A	N/A	N/A
<b>Fire</b>	<ul style="list-style-type: none"> <li>• Users &amp; maintenance personnel</li> <li>• Burns</li> <li>• Asphyxiation from smoke/fumes</li> </ul>	<ul style="list-style-type: none"> <li>• A fire risk assessment has been carried out for the whole building, and suitable actions taken.</li> <li>• Weekly checks of fire alarms, fire doors and emergency lighting.</li> </ul>	N/A	N/A	N/A	N/A

<b>What are the hazards?</b>	<b>Who might be harmed and how?</b>	<b>What are we Already doing to control the risks?</b>	<b>What further action Do we need to take to control the risks?</b>	<b>Who needs to carry out the action?</b>	<b>When is the action needed by?</b>	<b>Done</b>
<b>Legionella</b>	<ul style="list-style-type: none"> <li>• Users of the water system,</li> </ul>	<ul style="list-style-type: none"> <li>• Cold water is straight from the mains supply.</li> </ul>	N/A	N/A	N/A	N/A
<b>Vandalism</b>	<ul style="list-style-type: none"> <li>• Users &amp; maintenance personnel</li> <li>• Injury from broken seats or washbasin</li> <li>• Injury from wet floor</li> </ul>	<ul style="list-style-type: none"> <li>• Toilet rolls and soap are attached to the walls. and other equipmen</li> <li>• Outside toilets are checked daily and cleaned as necessary, perhaps 3times per week</li> <li>• These will be locked if found to be blocked or vandalised, until they can be repaired.</li> </ul>	N/A	N/A	N/A	N/A